

## The Niagara Falls Water Board

# Frozen Waterline Investigation Report

**GGE 15-1032**

*Prepared for:*  
The Niagara Falls Water Board



*Prepared by:*  
Glynn Geotechnical Engineering  
415 South Transit Street  
Lockport, New York 14094



September 2, 2015

---

### GLYNN GEOTECHNICAL ENGINEERING

415 South Transit Street, Lockport, New York 14094  
voice 716.625.6933 / fax 716.625.6983  
[www.glynnngroup.com](http://www.glynnngroup.com)

# TABLE OF CONTENTS

Frozen Waterline Investigation Report  
The Niagara Falls Water Board  
GGE 15-1032

September 2, 2015  
TOC

## REPORT

### EXECUTIVE SUMMARY

- 1.0 INTRODUCTION
- 2.0 INVESTIGATION PROCEDURE
- 3.0 INVESTIGATION FINDINGS
- 4.0 EVALUATION OF FINDINGS
- 5.0 RECOMMENDATIONS
- 6.0 CONCLUSION

## APPENDICES

- A Waterline Service Lateral Profiles
- B Exhibit 1 – 72<sup>nd</sup> Street Reconstruction Cross Section
- C Calculations – Insulation Loss
- D Table 2.0 – 72<sup>nd</sup> Street Frozen Water Service vs Change in Street Level
- E Exhibit 2 – Water Service Tap Relocation
- F 2015 NFWB Frozen Service Log
- G 2015 NFWB Frozen Water Service Map
- H 72<sup>nd</sup> Street Repaving Contract Drawings (15 Sheets)
- I GGE Laboratory Test Results
- J Field Observation Reports

## EXECUTIVE SUMMARY

A study of the frozen waterlines, particularly the service laterals, has been completed by Glynn Geotechnical Engineering (GGE) on behalf of the Niagara Falls Water Board (NFWB). This study effort included 1.) the review of reports of frozen waterlines for 2015, 2.) engineering drawings for the reconstruction of 72<sup>nd</sup> Street, 3.) finding of the excavation and examination of waterline services in ten (10) locations within the City of Niagara Falls and 4.) consideration of historical temperature records for the winter of 2015.

It is our opinion, formulated from the study efforts that:

- 1.) During the month of February 2015 Western New York experienced the coldest temperatures on record. The average temperature for the entire month of February 2015 was 11.1 degrees Fahrenheit, whereas the average temperature for the month, prior to 2015, was 26.3 degrees Fahrenheit. The extremely low temperature period was the principal cause of the frozen waterlines.
- 2.) The reconstruction of 72<sup>nd</sup> Street decreased the insulation protection of the waterlines by the replacement of clayey soils with crushed stone by a factor of 30%.
- 3.) For the most part the original waterlines, mains and service laterals, in the City of Niagara Falls are not buried to the minimum recommended frost depth of 48 inches.
- 4.) The problem of frozen waterline lines was limited to the service lateral from the main to the curb box. The freezing conditions have not impacted the water mains.
- 5.) There are multiple conditions responsible for the various frozen waterlines.

## 1.0 INTRODUCTION

During the winter of 2014, and again in the winter of 2015, there have been numerous instances of frozen water services in the City of Niagara Falls, New York. The residences affected by the frozen water service condition have occurred in clusters as well as in scattered neighborhoods, including a number of residences on the 500 and 600 blocks of 72<sup>nd</sup> Street, where the street was reconstructed in 2013.

In an attempt to resolve the lack of water supply to residences the NFWB (owner of the water utilities) initiated a "drip program", wherein the homeowner keeps a faucet turned on to keep the water moving in the service line. In cases where the residence water service has already frozen, the NFWB established a temporary connection from a neighboring residence. In certain instances the service lines were thawed out by inserting a small steam pipe into the line.



Because the frozen water service issue was a significant problem in 2014 and reoccurred in 2015, the NFWB retained the services of GGE to conduct a study of the conditions and factors related to the problem in an attempt to understand the issues and formulate a solution. GGE examined the data related to the frozen water services, gathered by the NFWB, and investigated the underground conditions of several residential locations spread across the City. By means of test pits, GGE documented the depth of the water mains and the lateral piping from the connection of the service lateral at the water main to the curb box / valve. GGE has completed the field investigation effort and prepared this report of our findings.

## 2.0 INVESTIGATION PROCEDURE

In order to provide a representative cross section of the residential service lateral conditions, GGE reviewed the historical data regarding location and dates of freezing water lines and selected ten (10) sites for investigation. Sites were selected in an effort to represent a variety of scenarios throughout the City, including frozen and non-frozen line locations, early and late reporting dates, long and short service lateral lengths (from the valve box to the curb) and new and old roadway construction.

The investigation was performed by GGE's excavation subcontractor, J.R. Swanson Plumbing Company, Inc. (Swanson), from May 27 through July 22, 2015. The investigation effort was observed and directed by GGE engineers and geologists. Swanson performed the excavation using Kubota U55 tracked excavator and manual excavation with hand tools. The excavations were primarily backfilled with compacted 2 inch run of crusher stone. Clay soil was replaced directly over the waterline if encountered during excavation. Temporary cold patch asphalt was placed to match the existing roadway surface upon the completion of backfill operations. Excavation operation and investigation specifics were recorded by GGE on the Field Observation Reports included in Appendix J.

The sites selected by GGE, which were chosen in an effort to gain as much data as possible, are identified in Table 1.0 on the following page. The table provides the reason the location was selected for investigation and a comment about the particular findings at that location. Detailed cross sections of the underground conditions encountered during the investigation at each location are included in Appendix A. In addition to the test pit excavations performed at each of the ten (10) locations, GGE reviewed 1.) the reconstruction plans for 72<sup>nd</sup> Street, 2.) the insulating properties of clay soil and crushed stone and 3.) common practices employed by plumbers to thaw frozen waterlines.



TABLE 1.0  
CITY OF NIAGARA FALLS FROZEN WATERLINE STUDY  
EXCAVATION SITES  
GGE 15-1032

PROFILE	LOCATION	SELECTION CRITERIA	COMMENTS
<b>P8</b>	<b>1).</b> 2926 Ontario Avenue	Reported frozen condition early during records, February 16, 2015: Within a cluster area.	2'-9" Cover at main, main buried in stone.
<b>P5</b>	<b>2).</b> 1906 Welch Avenue	One of last locations to report frozen condition, March 1, 2015.	2'-9" Cover at main, lots of clay cover.
<b>P2</b>	<b>3).</b> 511 72 <sup>nd</sup> Street	Shallow valve box depth, located on 72 <sup>nd</sup> Street.	2'-5" Cover at main, less than 1" change in street elevation, mostly stone backfill.
<b>P1</b>	<b>4).</b> 602 72 <sup>nd</sup> Street	Deepest valve box depth, located on 72 <sup>nd</sup> Street.	2'-9" Cover at main, approx 6" change in street elevation, mostly stone backfill.
<b>P6</b>	<b>5).</b> 1224 13 <sup>th</sup> Street	Included on drip program, likely frozen in 2014.	3'-2" Cover at main, lots of clay cover, not below frost depth.
<b>P3</b>	<b>6).</b> 490 77 <sup>th</sup> Street	Included on drip program, likely frozen in 2014.	3'-1", decrease to 2'-5", crosses storm sewer.
<b>P4</b>	<b>7).</b> 619 26 <sup>th</sup> Street	Located in a cluster area.	3'-5" Cover at main, 3'-0" cover at valve box, mostly stone backfill.
<b>P9</b>	<b>8).</b> 2929 20 <sup>th</sup> Street	Random selection, new construction.	3'-8" Cover at main, 5'-1" cover at valve box, mostly stone backfill.
<b>P10</b>	<b>9).</b> 571 77 <sup>th</sup> Street	Any house, near cluster, did not freeze in 2015.	3'-0" Cover at main 3'-2" cover at valve box, short side, 8"± clay backfill.
<b>P7</b>	<b>10).</b> 1358 Michigan Avenue	Away from a cluster, did not freeze in 2015.	4'-1" Cover at main, 3'-11" at valve box, mostly clay backfill.

Selection criteria attempts to choose locations that represent the full spectrum of conditions and locations distributed throughout the City.

### 3.0 INVESTIGATION FINDINGS

Results of the test excavations are shown on the profile drawings included under Appendix A. Findings from the test excavation were generally as anticipated.

The service laterals in the City of Niagara Falls are generally located on the top of the water main pipe. The geometry of this detail results in the service connection having 6 to 10 inches less backfill cover than the mainline and hence less frost protection.

Of the sites investigated, 80 % of the original water mains were located at a depth less than the recommended 48 inch frost depth, the remaining 20 % were located at depths of 50 and 55 inches. However, due to the connection of the service lateral made at the top of the water main, the burial depth of the service laterals was found to comply with the recommended burial depth at only one location, or 10 % of the time. In the two locations that did not report frozen piping last year, the service laterals were generally buried deeper than the majority of other sites (4'-1" and 3'-0"), the backfill included a considerable measure of clay backfill (2'-11" and 0'-8") and / or the residence was on the same side of the street as the water main and therefore only 5' from the street curb. Those investigated services, on the NFWB frozen service log, that were backfilled primarily with crushed stone or were found at a relatively shallow depth tended to be reported early during the crisis period.

The service at 490 77<sup>th</sup> Street was found to rest directly on the top of a storm sewer. The direct exposure to near ambient air temperatures indicates a situation that answers the riddle of why this service freezes.

The water main on 72<sup>nd</sup> Street, at the two investigated sites, was measured at 3' – 3" below the surface of the pavement. At these locations the street surface was lowered less than 1 inch at house 511 and approximately 6 inches at house 602. At house 511 the service lateral was measured at 2' – 5" below the street at the connection to the water main, whereas at house 602 the service lateral was found 2' – 9" below the street at the connection to the water main (Refer to profile drawings P1 and P2). Our investigation results revealed at house 511 there was only 1 inch of clay soil over the service lateral at the water main connection and at house 602 there was only 6 inches of clay soil over the service lateral at the water main connection.

### 4.0 EVALUATION OF FINDINGS

There are patterns associated with the frozen water services based on the findings of this study. Shallow depth of cover over the services lines, coupled with little to no clay backfill, was found in 50% of the excavated locations reporting a frozen water service in 2015. Of the remaining locations investigated, that reported a frozen water service in 2015, the depth of the lateral at the connection to the water main varied from 2' – 9" to 3' – 2".

Reconstruction of 72<sup>nd</sup> Street resulted in the replacement of approximately 17" of clay with crushed stone (refer to Exhibit 1 in Appendix B). Removal of the clay, which is an excellent insulating material, and replacement with crushed stone, which is a poor insulating material, resulted a 30 % loss of insulating value in the backfill over the main and lateral piping (refer to calculations in Appendix C). Although there were four homes along 72<sup>nd</sup> Street where the road was lowered by 6 inches, and hence the cover over the waterline decreased by this amount, there were seven homes that reported frozen waterlines where the street level was lowered by only 1 inch or less (refer to Table 2.0 in Appendix D). It is apparent therefore, that replacement of the clay soil with crushed stone was the principal factor causing the 25 residences on 72<sup>nd</sup> Street to experience frozen water services, not the lowering of the street grade.

## 5.0 RECOMMENDATIONS

The National Weather Service has forecast the 2016 winter temperatures will be a repeat of the 2014 and 2015 bitter cold. The Niagara Falls Water Board should make preparations during the next few months to deal with the inevitable frozen water service condition in the upcoming winter. The drip program should be continued, coupled with educating the public on how important it is to keep a steady stream of water running. Also, the NFWB should consider going out for proposals for 2 or 3 local plumbers to be on call to react to the anticipated demand for thawing pipes and making supply connections with neighbors. In the long term the NFWB should proceed to reduce the potential for repeated frozen water services by adopting a proactive program including the following efforts:

- 1.) Make sure the residential valve boxes are fully open.
- 2.) Promote an alternate street reconstruction design that does not diminish the insulation of the piping. Alternatively, lower water mains during street reconstruction if clay backfill is removed or lessened significantly.
- 3.) When work is performed on a service lateral relocate the service connection from the top of the water main to the bottom quadrant, thereby increasing the depth of cover over the service lateral by several inches. (See detail in appendix 5.0)

## 5.0 CONCLUSIONS

The primary source of frozen waterline conditions throughout the City of Niagara Falls within the past two years has been the bitter cold temperatures. As previously stated, the Western New York region has experienced some of the coldest temperatures on record. However, notwithstanding the colder than average temperatures, the following secondary conditions have served to directly influence the increased potential for waterlines to freeze:



1. The entire length of the service lateral, or a portion of the service lateral length, is buried above the prescribed frost depth of 48 inches for the City of Niagara Falls. In addition, 80 % of the water mains investigated were installed with less than 48 inches of cover over the top of the pipe.
2. The service lateral was backfilled with crushed stone, which exhibits poor insulating properties, as opposed to clay soil, which exhibits good insulating properties. This is very evident along 72<sup>nd</sup> Street where clay soils were removed during road reconstruction and replaced with crushed stone, therefore increasing the frost penetration potential.
3. The current location of the service lateral tap at the top of the water main results in a rise in elevation of the service lateral, providing greater freezing potential. When the opportunity arises the tap for the service lateral should be relocated to the side or bottom of the main at problem locations.
4. Service laterals that have to span the entire length of the street have a higher potential to freeze than service laterals that only run a short distance beneath the street. This is particularly an issue where insufficient cover or poor insulating backfill is present.
5. The location of the service lateral over the storm sewer provides for exposure to ambient air temperatures and increased freezing potential. The service lateral should always be installed beneath the storm sewer piping.

Sincerely,



Mark W, Glynn, P.E.  
Consulting Engineer, Principal

# Appendix A


## Waterline Service Lateral Profiles

### Frozen Waterline Investigation Report

The Niagara Falls Water Board


GGE 15-1032

September 2, 2015



# WATERLINE SERVICE LATERAL PROFILE

SCALE: 1/2" = 1'-0" ON 11 X 17



# WATERLINE SERVICE LATERAL PROFILE

SCALE: 1/2" = 1'-0" ON 11 X 17

KEY	
	2" ROC STONE
	ROC STONE W/ COBBLES
	CLAY SOIL
	CONCRETE
	GEOGRID MAT
	GEOTEXTILE FABRIC
	ASPHALT PAVEMENT

**CIVIL • STRUCTURAL • GEOTECHNICAL**  
**MATERIALS TESTING • CONSULTING**

**GLYNN GEOTECHNICAL ENGINEERING**  
415 S. TRANSIT STREET  
LOCKPORT, NEW YORK 14094  
www.glynngrp.com  
VOICE (716) 625 - 6933 / FAX (716) 625 - 6983

GGE PROJ. #	15-1032
FILE NAME:	profiles
DATE:	08.27.15
DRAWN BY:	GEL
CHECKED BY:	MWG

CLIENT:

NIAGARA FALLS WATER BOARD

PROJECT:

NIAGARA FALLS WATERLINE INVESTIGATION


DWG:

p1

TITLE:

602 72ND STREET PROFILE






**WATERLINE SERVICE LATERAL PROFILE**  
SCALE: 1/2" = 1'-0" ON 11 X 17

**KEY**


	2" ROC STONE
	ROC STONE W/ COBBLES
	CLAY SOIL
	CONCRETE
	GEOGRID MAT
	GEOTEXTILE FABRIC
	ASPHALT PAVEMENT

CLIENT: <b>NIAGARA FALLS WATER BOARD</b>	PROJECT: <b>NIAGARA FALLS WATERLINE INVESTIGATION</b>	GSE PROJ. # 15-1032 FILE NAME: profiles DATE: 08.27.15 DRAWN BY: GEL CHECKED BY: MVG		GLYNN GEOTECHNICAL ENGINEERING 415 S. TRANSIT STREET LOCKPORT, NEW YORK 14094 www.glynngrp.com VOICE (716) 625 - 6933 / FAX (716) 625 - 6983
DWG: <b>P2</b>	TITLE: <b>511 72ND STREET PROFILE</b>			



## WATERLINE SERVICE LATERAL PROFILE


SCALE: 1/2" = 1'-0" ON 11 X 17




## WATERLINE SERVICE LATERAL PROFILE

SCALE: 1/2" = 1'-0" ON 11 X 17


### KEY




2" ROC STONE



ROC STONE W/ COBBLES



CLAY SOIL




CONCRETE



GEOGRID MAT



GEOTEXTILE FABRIC



#1 STONE



ASPHALT PAVEMENT




**GLYNN GEOTECHNICAL ENGINEERING**  
 CIVIL • STRUCTURAL • GEOTECHNICAL  
 MATERIALS TESTING • CONSULTING

**GLYNN GEOTECHNICAL ENGINEERING**  
 415 S. TRANSIT STREET  
 LOCKPORT, NEW YORK 14094  
[www.glynngrp.com](http://www.glynngrp.com)  
 VOICE (716) 625 - 6933 / FAX (716) 625 - 6983


GCE PROJ. # 15-1032	FILE NAME: profiles	DATE: 08.27.15	DRAWN BY: GEL	CHECKED BY: MWG
------------------------	------------------------	-------------------	------------------	--------------------

CLIENT: <b>NIAGARA FALLS WATER BOARD</b> PROJECT: <b>NIAGARA FALLS WATERLINE          INVESTIGATION</b>	TITLE: <b>490 77TH STREET PROFILE</b> DWG : <div style="font-size: 2em; font-weight: bold; display: inline-block;">P3</div>
--	--



## WATERLINE SERVICE LATERAL PROFILE


SCALE: 1/2" = 1'-0" ON 11 X 17




## WATERLINE SERVICE LATERAL PROFILE

SCALE: 1/2" = 1'-0" ON 11 X 17


### KEY




2" ROC STONE




ROC STONE W/ COBBLES



CLAY SOIL



CONCRETE



ASPHALT PAVEMENT

**GCE**  
CIVIL • STRUCTURAL • GEOTECHNICAL  
MATERIALS TESTING • CONSULTING

GLYNN GEOTECHNICAL ENGINEERING  
415 S. TRANST. STREET  
LOCKPORT, NEW YORK 14094  
www.glynngrp.com  
VOICE (716) 625 - 6933 / FAX (716) 625 - 6983

GCE PROJ. #  
15-1032  
FILE NAME:  
profiles  
DATE:  
08.27.15  
DRAWN BY:  
GEL  
CHECKED BY:  
MWG

CLIENT:  
NIAGARA FALLS WATER BOARD  
PROJECT:  
NIAGARA FALLS WATERLINE  
INVESTIGATION


TITLE:  
619 26TH STREET PROFILE

DWG.:  
p4




# WATERLINE SERVICE LATERAL PROFILE


SCALE: 1/2" = 1'-0" ON 11 X 17



## KEY



GRAVEL




CLAY SOIL



CONCRETE



ASPHALT PAVEMENT



BRICK

CLIENT:

NIAGARA FALLS WATER BOARD

PROJECT:

NIAGARA FALLS WATERLINE  
INVESTIGATION

DWG:

P5

TITLE:

1906 WELCH AVENUE PROFILE

GGE PROJ. #

15-1032

FILE NAME:

profiles

DATE:

08.27.15

DRAWN BY:

GEL

CHECKED BY:

MWG




CIVIL • STRUCTURAL • GEOTECHNICAL  
MATERIALS TESTING • CONSULTING

GLYNN GEOTECHNICAL ENGINEERING

415 S. TRANSIT STREET  
LOCKPORT, NEW YORK 14094


www.glynngrp.com

VOICE (716) 625 - 6933 / FAX (716) 625 - 6983



**WATERLINE SERVICE LATERAL PROFILE**


SCALE: 1/2" = 1'-0" ON 11 X 17




**WATERLINE SERVICE LATERAL PROFILE**

SCALE: 1/2" = 1'-0" ON 11 X 17

**KEY**




2" ROC STONE



CLAY SOIL



CONCRETE




BRICK



ASPHALT PAVEMENT

CIVIL • STRUCTURAL • GEOTECHNICAL  
MATERIALS TESTING • CONSULTING

GLYNN GEOTECHNICAL ENGINEERING  
415 S. TRANSIT STREET  
LOCKPORT, NEW YORK 14094  
www.glynngrp.com  
VOICE (716) 625-6933 / FAX (716) 625-6983



G&E PROJ. # 15-1032	FILE NAME: profiles	DATE: 08.27.15	DRAWN BY: GEL	CHECKED BY: MWG
------------------------	------------------------	-------------------	------------------	--------------------

CLIENT:  
NIAGARA FALLS WATER BOARD


PROJECT:  
NIAGARA FALLS WATERLINE  
INVESTIGATION

TITLE:  
1224 13TH STREET PROFILE


DWG:  
P6

# WATERLINE SERVICE LATERAL PROFILE


SCALE: 1/2" = 1'-0" ON 11 X 17



## KEY



CLAY SOIL



CONCRETE



ASPHALT PAVEMENT

CLIENT:

NIAGARA FALLS WATER BOARD

PROJECT:

NIAGARA FALLS WATERLINE  
INVESTIGATION

DWG:

P7

TITLE:

1358 MICHIGAN AVENUE PROFILE

COE PROJ. #

15-1032

FILE NAME:

profiles

DATE:

08.27.15

DRAWN BY:

GEL

CHECKED BY:

MWG





CIVIL • STRUCTURAL • GEOTECHNICAL  
MATERIALS TESTING • CONSULTING

GLYNN GEOTECHNICAL ENGINEERING

415 S. TRANSIT STREET  
LOCKPORT, NEW YORK 14094  
www.glyngroup.com

VOICE (716) 625 - 6933 / FAX (716) 625 - 6983





## WATERLINE SERVICE LATERAL PROFILE

SCALE: 1/2" = 1'-0" ON 11 X 17

CLIENT:

NIAGARA FALLS WATER BOARD

PROJECT:

NIAGARA FALLS WATERLINE  
INVESTIGATION

DWG:

p8

TITLE:

2926 ONTARIO AVENUE PROFILE

GSE PROJ. #

15-1032

FILE NAME:

profiles

DATE:

08.27.15

DRAWN BY:

GEL

CHECKED BY:

MWVG



CIVIL • STRUCTURAL • GEOTECHNICAL  
MATERIALS TESTING • CONSULTING


GLYNN GEOTECHNICAL ENGINEERING

415 S. TRANSIT STREET

LOCKPORT, NEW YORK 14094


www.glynneng.com

VOICE (716) 625 - 6933 / FAX (716) 625 - 6983



## WATERLINE SERVICE LATERAL PROFILE


SCALE: 1/2" = 1'-0" ON 11 X 17




## WATERLINE SERVICE LATERAL PROFILE

SCALE: 1/2" = 1'-0" ON 11 X 17


### KEY



2" ROC STONE



CLAY SOIL



CONCRETE



ASPHALT PAVEMENT

**GCE**

CIVIL • STRUCTURAL • GEOTECHNICAL  
MATERIALS TESTING • CONSULTING

GLYNN GEOTECHNICAL ENGINEERING  
415 S. TRANSIT STREET  
LOCKPORT, NEW YORK 14094  
www.glynngrp.com  
VOICE (716) 625 - 6933 / FAX (716) 625 - 6983

GCE PROJ. #  
15-1032

FILE NAME:  
profiles

DATE:  
08.27.15

DRAWN BY:  
GEL

CHECKED BY:  
MWG

CLIENT:  
NIAGARA FALLS WATER BOARD



PROJECT:  
NIAGARA FALLS WATERLINE  
INVESTIGATION

TITLE:  
2929 20TH STREET PROFILE

DWG: **P9**

WATERLINE SERVICE LATERAL PROFILE

SCALE: 1/2" = 1'-0" ON 11 X 17



CLIENT: NIAGARA FALLS WATER BOARD	PROJECT: NIAGARA FALLS WATERLINE INVESTIGATION	DWG.: P10	TITLE: 571 77TH STREET PROFILE
GGE PROJ. # 15-1032 FILE NAME: profiles DATE: 08.27.15 DRAWN BY: GEL CHECKED BY: MWG			
GLYNN GEOTECHNICAL ENGINEERING CIVIL • STRUCTURAL • GEOTECHNICAL MATERIALS TESTING • CONSULTING 415 S. TRANSIT STREET LOCKPORT, NEW YORK 14094 www.glynngrp.com VOICE (716) 625 - 6933 / FAX (716) 625 - 6983			



a member of the GLYNN GROUP

Civil • Structural • Geotechnical • Materials Testing • Consulting

# Appendix B

## Exhibit 1 – 72<sup>nd</sup> Street Reconstruction Cross Section

Frozen Waterline Investigation Report

The Niagara Falls Water Board

GGE 15-1032


September 2, 2015

---

### GLYNN GEOTECHNICAL ENGINEERING

415 South Transit Street, Lockport, New York 14094  
voice 716.625.6933 / fax 716.625.6983  
[www.glynnngroup.com](http://www.glynnngroup.com)






## 72nd STREET RECONSTRUCTION CROSS SECTIONS



SCALE: 1-1/2" = 1'-0"

 <b>ENGINEERING • DESIGN</b> GLYNN GEOTECHNICAL ENGINEERING 415 S. TRANSIT STREET LOCKPORT, NEW YORK 14094 VOICE (716) 625 - 6933 / FAX (716) 625-6983 www.glynngroup.com	PROJECT: NIAGARA FALLS WATERLINE			SHEET NO.:  <b>EXHIBIT</b>  <b>1</b>
	SUBJECT: 72nd STREET CROSS SECTION			
	CLIENT: NFWB			
	PROJ. NO.: 15-1032	SCALE: 1-1/2"=1'	DATE: 9.2.15	BY: MWG

# Appendix C

## Calculation – Insulation Loss

Frozen Waterline Investigation Report

The Niagara Falls Water Board

GGE 15-1032

September 2, 2015

# LATENT HEAT OF BACKFILL MATERIALS

## CRUSHED STONE

- EST. UNIT WT 145 PCF
- EST NATURAL MOISTURE CONTENT 8% - CONSERVATIVE  
 $8\% \times 145 = 11.6 \text{ PCF}$
- MINERAL PORTION  
 $0.2 \text{ BTU} \times 145 \text{ PCF} = 29 \text{ BTU}$
- WATER PORTION  
 $144 \text{ BTU} \times 11.6 \text{ PCF} = 1670.4 \text{ BTU}$
- TOTAL  $29 + 1670.4 = 1699.4 \text{ BTU / CF}$

## CLAY / SOIL

- EST UNIT WT. 100 PCF
- NATURAL MOISTURE CONTENT 24% PER GGE LAB TEST  
 $24\% \times 100 = 24 \text{ PCF}$
- MINERAL PORTION  
 $0.2 \text{ BTU} \times 100 \text{ PCF} = 20 \text{ BTU}$
- WATER PORTION  
 $144 \text{ BTU} \times 24 \text{ PCF} = 3456 \text{ BTU}$
- TOTAL  $20 + 3456 = 3476 \text{ BTU / CF}$



ENGINEERING DESIGN

GLYNN GEOTECHNICAL ENGINEERING

415 South Transit Street  
Lockport, New York 14094

voice 716.625.6933 / fax 716.625.6983  
www.glynnngroup.com

PROJECT:

NFWB FROZEN WATERLINE STUDY

SUBJECT:

CALCULATION - INSULATION LOSS

CLIENT:

NFWB

PROJECT NO:

15-1032

SCALE:

N.A.

DATE:

8.27.15

BY:

LAWS

SHEET NO:

APPEN.

3.0

SHT. 1  
of 2



# LATENT HEAT OF BACKFILL MATERIALS

## NEW CONSTRUCTION SECTION

$$34.5" \text{ PAVEMENT} = 2.875'$$

$$4.5" \text{ CLAY SOIL} = 0.375'$$

$$\text{LATENT HEAT } 2.875' \times 1699.4 \text{ BTU/CF} + 0.375' \times 3476 \text{ BTU/CF} \\ = 6189.275 \text{ BTU}$$

## OLD CONSTRUCTION SECTION

$$17" \text{ PAVEMENT} = 1.42'$$

$$22" \text{ CLAY} = 1.83'$$

$$\text{LATENT HEAT } 1.42' \times 1699.4 \text{ BTU/CF} + 1.83' \times 3476 \text{ BTU/CF} \\ = 8774.23 \text{ BTU}$$

DECREASE OF LATENT HEAT IN BACKFILL:

$$6189.3 \div 8774.2 = 0.705, 70.5\%$$

$$100.0\% - 70.5\% = 29.5\% \text{ LOSS}$$



ENGINEERING DESIGN

GLYNN GEOTECHNICAL ENGINEERING

415 South Transit Street  
Lockport, New York 14094

voice 716.625.6933 / fax 716.625.6983  
www.glynnngroup.com

PROJECT: **NFWB FROZEN WATERLINE STUDY**

SUBJECT: **CALCULATION - INSULATION LOSS**

CLIENT: **NFWB**

PROJECT NO:  
**15-1032**

SCALE:  
**NA**

DATE:  
**8.27.15**

BY: **AWG**

SHEET NO:

**APPEN.  
3.0  
SHT. 2  
of 2**





a member of the GLYNN GROUP

Civil • Structural • Geotechnical • Materials Testing • Consulting

# Appendix D

## Table 2.0 – 72<sup>nd</sup> Street Frozen Water Services vs Change in Street Level

Frozen Waterline Investigation Report

The Niagara Falls Water Board

GGE 15-1032

September 2, 2015

---

### GLYNN GEOTECHNICAL ENGINEERING

415 South Transit Street, Lockport, New York 14094  
voice 716.625.6933 / fax 716.625.6983  
[www.glynngroup.com](http://www.glynngroup.com)

**TABLE 2.0 – 72<sup>ND</sup> STREET SERVICES**  
**GGE 15-1032**

<b>Report Date</b>	<b>House No.</b>	<b>Change in Street Level</b>
2/19/15	607	6"
2/19/15	572	No such address
2/20/15	502	Less than 3"
2/20/15	603	6"
2/22/15	500	No such address
2/22/15	501	Less than 3"
2/22/15	512	Less than 1"
2/22/15	513	Less than 1"
2/22/15	521	Less than 1"
2/22/15	546	Less than 3"
2/22/15	550	Less than 3"
2/22/15	625	Less than 3"
2/22/15	629	Less than 3"
2/22/15	646	Less than 4"
2/23/15	651	Less than 1"
2/23/15	602	6"
2/23/15	513	Less than 1"
2/23/15	528	Less than 1"
2/25/15	636	Less than 2"
2/25/15	660	No change
2/26/15	622	Less than 3"
2/26/15	643	Less than 4"
3/2/15	570	Less than 3"
3/2/15	650	Less than 2"
3/3/15	638	Less than 4"
3/3/15	644	No such address
3/3/15	650	Less than 3"
3/5/15	532	Less than 6"



# Appendix E

## Exhibit 2 – Water Service Tap Relocation

Frozen Waterline Investigation Report

The Niagara Falls Water Board


GGE 15-1032

September 2, 2015

---

### GLYNN GEOTECHNICAL ENGINEERING

415 South Transit Street, Lockport, New York 14094  
voice 716.625.6933 / fax 716.625.6983  
[www.glynngroup.com](http://www.glynngroup.com)



A  
EX2

## WATER SERVICE TAP RELOCATION

SCALE: N/A

**GGE**

ENGINEERING • DESIGN

GLYNN GEOTECHNICAL ENGINEERING

415 S. TRANSIT STREET

LOCKPORT, NEW YORK 14094

VOICE (716) 625-6933 / FAX (716) 625-6983

www.glynngroup.com

PROJECT:

NIAGARA FALLS WATERLINE

SUBJECT:

SERVICE CONNECTIONS

CLIENT:

NFWB

PROJ. NO.:

15-1032

SCALE:

NA

DATE:

9.2.15

BY:

GEL/MWG

SHEET NO.:

EXHIBIT

2





a member of the GLYNN GROUP

Civil • Structural • Geotechnical • Materials Testing • Consulting

# Appendix F

## 2015 NFWB Frozen Service Log

Frozen Waterline Investigation Report

The Niagara Falls Water Board

GGE 15-1032

September 2, 2015

---

### GLYNN GEOTECHNICAL ENGINEERING

415 South Transit Street, Lockport, New York 14094  
voice 716.625.6933 / fax 716.625.6983  
[www.glynngroup.com](http://www.glynngroup.com)

# 2015 Frozen Service Log

	Date	House #	Street	Reported By	On Drip Prog? Yes = 1	Hose Ran? Yes = 1	Status
1	2/16/2015	911	22nd				Owner never called back with neighbor info
2		2120	Hyde Park				Has water was a internal problem
3		1808	Hyde Park		1		Can't do a hose run
4		3655	Ferry Ave				Plumber thawed service
5		2926	Ontario Ave				Nobody home
6		1605	Pine Ave				Can't do a hose run
7	2/19/2015	490	77th		1	1	
8		631	66th			1	Hose Froze 3 different times - 2 neighbors
9		9115	Buffalo Ave			1	
10		3337	Royal Ave		1	1	
11		137	76th		1	1	
12		607	72nd		1	1	
13		572	72nd		1	1	
14		578	79th		1	1	
15		329	37th		1	1	Hose froze - Replaced 2-25-15
16		624	28th		1	1	
17		2203	South Ave				House has water was a internal problem
18	2/20/2015	1616	Ontario Ave				Can't do a hose run-broken hose bib
19		1833	Pierce Ave				Can't do a hose run
20		140	77th				Was a frozen meter
21		832	20th				Nobody home
22		2781	Main St.				House has water was a internal problem
23		1921	Pine Ave				Frozen Meter-Interior pipes all frozen
24		576-578	7th				No hose bibs
25		535	66th			1	N such address-New building going up here
26		2246	Independence				
27		329	37th		1	1	House has water
28		1901	Pine Ave				No hose bibs
29		1905	Pine Ave				No hose bibs
30		1909	Pine Ave				No hose bibs
31		1421	22nd				Frozen Service - Owner is in the hospital
32		7021	Frontier Ave				House has water
#REF!		675	Ashland Ave				Was frozen inside
#REF!		502	72nd		1		Plumber thawed service
#REF!		1801	Niagara St				No neighbor
#REF!		1224	13th		1		
#REF!		521	29th				House never lost water
#REF!		521	Tronolone				No hose bibs
#REF!		7412	Frontier Ave			1	
#REF!		2453	Independence		1	1	

#REF!	603	72nd	1	Can't do a hose run
#REF!	1107	13th		Was an internal problem
#REF!	703	66th		Plumber thawed service
#REF!	500	72nd		Plumber thawed service
#REF!	501	72nd		Plumber thawed service
#REF!	512	72nd		1 Ran hose then Owner hired plumber to thaw
#REF!	513	72nd		Plumber thawed service
#REF!	521	72nd		1
#REF!	546	72nd		1 2 hose runs froze
#REF!	550	72nd		1 2nd hose run done
#REF!	625	72nd	1	1
#REF!	629	72nd	1	1 Nobody home
#REF!	646	72nd	1	1
#REF!	3662	Ferry Ave		1 Nobody home
#REF!	3617	Dudley Ave	1	
#REF!	651	72nd	1	1
#REF!	3658	Ferry Ave		Plumber thawed service
#REF!	4301	Lewiston Rd		Plumber thawed service
#REF!	1412 1/2	Ferry Ave		Back House frozen.Front house vacant
#REF!	1429	99th		Plumber thawed service
#REF!	619	Orchard Parkway		Plumber thawed service
#REF!	149	22nd		
#REF!	2929	20th		
#REF!	422	77th	1	No hose bibs
#REF!	521	Memorial Parkway		House has water - was an internal problem
#REF!	8423	Lindbergh Ave	1	No Neighbor
#REF!	4225	Hyde Park		Has water was a frozen Meter
#REF!	3227	Royal Ave	1	
#REF!	642	21st	1	
#REF!	3046	Niagara St		
#REF!	3046	Frontier		No such address
#REF!	564	75th		No Neighbor
#REF!	3425	Royal Ave	1	No neighbor
#REF!	602	72nd	1	No neighbor
#REF!	513	72nd		Owner hired plumber to thaw
#REF!	528	72nd	1	
#REF!	3662	Ferry Ave		
#REF!	3668	Ferry Ave		
#REF!	2460	Grand Ave		
#REF!	1814	Hyde Park	1	1 Plumber thawed service- re-froze-hose run done
#REF!	1225	85th		Can't do a hose run
#REF!	2429	North Ave		Thawed service-Re-froze 3-2
#REF!	1421	Osborne Ct		
#REF!	582	77th	1	Vacant house
#REF!	3659	Ferry Ave		
#REF!	709	66th	1	1 703-66th can give water
#REF!	2/22/2015			
#REF!	2/23/2015			
#REF!	2/23/2015			
#REF!	2/24/2015			

#REF!	2311	Walnut Ave	1	1	They did their own hose run it loks like 3/4/15
#REF!	2524	Pine Ave			Can't do a hose run
#REF!	519	Memorial Pkwy			521-Memorial Pkwy can give water
#REF!	1823	Ontario Ave			Plumber thawed service
#REF!	7718	Lindbergh Ave			
#REF!	2526	Pine Ave			
#REF!	636	72nd	1		Can't do hose run
#REF!	425	Vanderbilt Ave			1 Can get water from 628-72nd
#REF!	2625	Ontario Ave			
#REF!	2735	Orleans Ave			1 They did their own hose run from 2619-Ontario
#REF!	660	72nd	1		Plumber thawed service
#REF!	3924	Deveaux St			1 664-72nd can give water
#REF!	8516	Munson Ave			
#REF!	2739	Lasalle Ave			1 8520-Munson can give water
#REF!	624	76th			Plumber thawed service
#REF!	2311	Hyde Park Blvd			
#REF!	306	24th			Has boiler system
#REF!	1212	96th			Plumber thawed service
#REF!	2470	Grand Ave			Plumber thawed service
#REF!	2473	Cudaback Ave			
#REF!	2703	Lasalle Ave			
#REF!	302	24th			Can't do a hose run
#REF!	2015	18th			
#REF!	1417	22nd			1 Very low pressure
#REF!	619	26th			1 623-26th can give water
#REF!	435	13th			
#REF!	615	Buffalo Ave			
#REF!	2240	Pine Ave	1		
#REF!	2429	North Ave			Plumber thawed service
#REF!	1647	Ontario Ave			Plumber thawed service
#REF!	2473	Grand Ave			House now has water..3/4/15
#REF!	8822	Pear Ave			
#REF!	1235	96th	1		
#REF!	8489	W. Rivershore Dr			1 They did their own hose run from 8485-W Rivershore
#REF!	2620	Walnut Ave			
#REF!	539	16th			
#REF!	1419	Falls	1		
#REF!	2220	Walnut Ave			
#REF!	622	72nd	1		1 618-72 can give water
#REF!	539	16th			
#REF!	668	77th			Plumber thawed service
#REF!	2533	Jerauld Ave			Plumber thawed service
#REF!	540	77th			1 548-77th can give water
#REF!	2217	Mackenna Ave			Plumber thawed service
#REF!	2920	20th			
#REF!	8822	Pear Ave			Plumber thawed service



#REF!	2529	Jerauld Ave		Plumber thawed service
#REF!	643	72nd		Plumber thawed service
#REF!	2463	Independence Ave		
#REF!	2209	Welch Ave		
#REF!	7525	Frontier Ave		Plumber thawed service
#REF!	780	Monteagle		
#REF!	624	74th St		
#REF!	2951	North Ave		Plumber thawed service
#REF!	1441	Ferry Ave		Landlord notified
#REF!	574	76th		Plumber thawed service
#REF!	365	70th		They did their own hose run from 362-71st
#REF!	552	18th		
#REF!	202	22nd		
#REF!	1522	Hyde Park		
#REF!	2471	Independence Ave		1
#REF!	2474	Independence Ave		1 They did their own hose run from 2466-Indep We removed register
#REF!	1915	Lasalle Ave		Has key to neighbors house for a hose run
#REF!	7811	Lindbergh Ave		Plumber thawed service
#REF!	236	84th		Plumber thawed service
#REF!	527	26th		1
#REF!	942	Niagara Ave		Service ok- Main break in street
#REF!	570	72nd		
#REF!	440	26th		
#REF!	2487	Grand Ave		Nobody home 3/7/15
#REF!	335	Buffalo Ave		
#REF!	9790	Cayuga Dr		
#REF!	2470	Independence Ave		1 They did their own hose run from 2466-Indep We removed register
#REF!	180	81st		Plumber thawed service
#REF!	3924	Deveaux St		Plumber thawed service
#REF!	1726	Elmwood Ave		
#REF!	2027	Hyde Park		Plumber thawed service
#REF!	2911	Ferry Ave		They did their own hose run 3/5/15
#REF!	2727	Livingston Ave		Plumber thawed service
#REF!	702	60th	1	Can't do a hose run
#REF!	2631	Ontario Ave		
#REF!	2468	Grand Ave		1
#REF!	623	81st		
#REF!	3070	Dorchester Rd		
#REF!	650	72nd	1	
#REF!	2213	Mackenna Ave		Plumber thawed service
#REF!	7806	Lindbergh Ave		1 Did there own hose run to 2449-Grand Ave
#REF!	2443	Grand Ave		Plumber thawed service
#REF!	2464	Grand Ave		1 3 weeks without water
#REF!	2659	Ontario Ave		Nobody home 3/7/15
#REF!	2463	Grand Ave		Plumber Thawed service
#REF!	638	72nd		

#REF!	644	72nd	Plumber thawed service	1	
#REF!	650	72nd			
#REF!	918	92nd	Plumber thawed service		
	740-750	Haberle Ave			
#REF!	7811	Lindbergh Ave	Plumber thawed service		
#REF!	2478	Grand Ave	Plumber thawed service		
	746	92nd			
	603	Vanderbilt Ave	Plumber thawed service		
	742	8th			
	2441	Grand Ave			
	6715	Lindbergh Ave	1 Did there own hose run from 2437-Grand		
	405	38th			
	462	20th	1 They did their own hose run		
	2645	North Ave	1		
	1030	99th	Plumber thawed service		
	2201	Independence Ave			
	2461	Independence Ave			
	2933	North Ave			
	2945	North Ave			
	1115	Vanderbilt Ave	1 They did their own hose run-We removed register @ 2935-North		
	1319-1329	Pine Ave	Plumber thawed service		
	2464	Grand Ave			
	2304	Pine Ave	Plumber thawed service		
	619	17th			
	608	72nd	Can't do a hose run- broken hose bib		
	825	87th	Plumber thawed service		
	700	Park Pl	418-Pine can give water		
	2457	Independence Ave			
	8001	Buffalo Ave	1 They did their own hose run		
	8503	Lindbergh Ave	Plumber thawed service		
	532	72nd	Plumber thawed service		
	3339	Church Ave			
	623	35th	Plumber thawed service		
	1018	Hyde Park			
	644	75th			
	2705	South Ave			
	1921	Pine Ave	No hose bibs		
	2903	Walnut Ave			
	531	73rd			
	609	Orchard Parkway			
	1380	Willow Ave			
	2414	Grand Ave			
	551	Main St.	Plumber thawed service		
	2486	Grand Ave	Plumber thawed service		
	1322	Willow Ave	They will wait until service thaws itself out		
	1401	Military Rd	Reeds Jewelers - Can't do a hose run		
	3/6/2015				
	3/9/2015				

3/10/2015	5657	Girard Ave
	335	Buffalo Ave
	1621	Pine Ave
	136	68th
3/11/2015	1915	Pine Ave
	760	10th
	2445	Independence Ave
	1906	Welch Ave

Trying to thaw service himself

140-68th can give water

Can't do a hose run



a member of the GLYNN GROUP

Civil • Structural • Geotechnical • Materials Testing • Consulting

# Appendix G

## 2015 NFWB Frozen Water Service Map

Frozen Waterline Investigation Report

The Niagara Falls Water Board

GGE 15-1032

September 2, 2015

---


### GLYNN GEOTECHNICAL ENGINEERING

415 South Transit Street, Lockport, New York 14094  
voice 716.625.6933 / fax 716.625.6983  
[www.glynnngroup.com](http://www.glynnngroup.com)



# Legend

■ Frozen Water Services



## 2015 Frozen Water Services

DISCLAIMER:  
FOR INFORMATION ONLY  
ACCURACY OF THIS PLAN  
SHALL BE CHECKED IN FIELD  
NIAGARA FALLS WATER BOARD

