



FOR IMMEDIATE RELEASE
January 20, 2018

Contact: Matt Davison
matt@martingroupmarketing.com
(716) 604-7772

*****Media Update & Official Statement*****

**Repair Update on Water Main Break at 47th Street and
Niagara Falls Boulevard in City of Niagara Falls**

The Niagara Falls Water Board (NFWB) continues to work toward total completion of major water main break repair in the vicinity of 47th Street and Niagara Falls Boulevard in the City of Niagara Falls. Now that physical repair is complete, the Department of Health requires testing of the water to ensure it meets all safety protocols. Lab testing takes roughly 48 hours, with results expected by Monday afternoon. Once cleared, the NFWB will slowly begin pressurizing the area, which is best practice and standard procedure. The full project is expected to reach completion, with restoration of normal water pressure for ratepayers by mid-to-late next week.

The NFWB will continue to provide updates as such information becomes available, via www.NFWB.org.

###